



## Technical Service Bulletin

Number TSB1-2

Date: 7/20/25

Purpose:  Critical firmware update  Hardware error  Mfg. error  Safety  Design improvement  
 other:

total number of attached pages: 0

images included

Nature of bulletin:

TM LITE Firmware error in v 1.76, which was causing pulse count issues when manually moving antenna up or down.

Product(s) affected:

TM LITE, s/n 2501650-2505695

Corrective action:

Contact factory for firmware update (no charge). Can be performed by customer, or optionally sent to factory